

## Timing Adjustment



Turn metering screw incrementally clockwise for longer flow time.



Turn metering screw incrementally counter clockwise for shorter flow time.

